


(IT) Istruzioni per l'uso  
(EN) Operating instructions**IST-ZX**  
05/2017**ZX**  
Pinza pneumatica  
autocentrale integrata con  
slitta**Self-centering pneumatic  
gripper with slide****Avvertenze**

Evitare il contatto con sostanze corrosive, spruzzi di saldatura, polveri abrasive, che potrebbero danneggiare la funzionalità dell'unità.

Per nessun motivo, persone od oggetti estranei devono entrare nel suo raggio d'azione.


L'unità non deve essere messa in servizio prima che la macchina di cui fa parte sia stata dichiarata conforme alle disposizioni di sicurezza vigenti.

**Mantenzione**

L'unità va ingrassata ogni 10 milioni di cicli con:

- BERULUB FG-H 2 EP (Lubrificante NSF H1 Registration No. 140486).


La pinza e la slitta in massima estensione hanno giochi inferiori a quelli qui indicati.

**Maintenance**

Grease the unit after 10 million cycles with:

- BERULUB FG-H 2 EP (Lubrificant NSF H1 Registration No. 140486).

For the gripper and the slide on maximum extension the backlashes are lower than those here indicated.

**Connessione pneumatica**

La pinza e la slitta si alimentano con aria compressa dai fori laterali montandovi i raccordi dell'aria M3 ed i relativi tubi (non forniti).

Aria compressa in S: apertura della pinza.  
Aria compressa in P: chiusura della pinza.  
Aria compressa in Q: estensione della slitta.  
Aria compressa in R: ritrazione della slitta.

L'unità è azionata con aria compressa filtrata (5-40 µm) non necessariamente lubrificata.

La scelta iniziale, lubrificata o non lubrificata, deve essere mantenuta per tutta la vita dell'unità.

L'impianto pneumatico deve essere pressurizzato gradualmente, per evitare movimenti incontrollati.

The compressed air must be filtered from 5 to 40 µm.

Maintain the medium selected at the start, lubricated or not, for the complete service life of the unit.


The pneumatic circuit must be pressurized progressively, to avoid uncontrolled movements.

The compressed air must be filtered from 5 to 40 µm.

Never let non-authorized persons or objects stand within the operating range of the unit.

Never let the unit come into contact with corrosive substances, soldering splashes or abrasive powders as they may damage the unit.

Never operate the unit if the machine on which it is fitted does not comply with safety laws and standards of your country.

**Circuito pneumatico**

Possibili inconvenienti sul circuito di alimentazione dell'aria compressa:


- 1- Oscillazioni di pressione.
- 2- Riempimento all'avvio.
- 3- Improvisa mancanza di pressione.
- 4- Eccessiva velocità di azionamento.

Possible solutions:

- 1- Compressed air storage (A).
- 2- Start-up valve (B).
- 3- Safety valve (C).
- 4- Flow controller (D).

Accorgimenti per risolvere i problemi:

- 1- Serbatoio esterno (A).
- 2- Valvola di avviamento progressivo (B).
- 3- Valvola di sicurezza (C).
- 4- Regolatori di flusso (D).

**Compressed air feeding**

The gripper and the slide are fed with compressed air through the side air ports with fittings M3 and relevant hoses (not supplied).

Compressed air in S: gripper opening.  
Compressed air in P: gripper closing.  
Compressed air in Q: extension of the slide.  
Compressed air in R: retraction of the slide.

The compressed air must be filtered from 5 to 40 µm.

Maintain the medium selected at the start, lubricated or not, for the complete service life of the unit.

The compressed air must be filtered from 5 to 40 µm.

The pneumatic circuit must be pressurized progressively, to avoid uncontrolled movements.

The compressed air must be filtered from 5 to 40 µm.

The compressed air must be filtered from 5 to 40 µm.

Never let the unit come into contact with corrosive substances, soldering splashes or abrasive powders as they may damage the unit.

Never let non-authorized persons or objects stand within the operating range of the unit.

Never operate the unit if the machine on which it is fitted does not comply with safety laws and standards of your country.

**Pneumatic circuit**

Possible problems on a compressed air circuit:


- 1- Pressure variation.
- 2- Pressurizing.
- 3- Sudden pressure black-out.
- 4- Excessive actuating speed.

Possible solutions:

- 1- Compressed air storage (A).
- 2- Start-up valve (B).
- 3- Safety valve (C).
- 4- Flow controller (D).

Accorgimenti per risolvere i problemi:

- 1- Serbatoio esterno (A).
- 2- Valvola di avviamento progressivo (B).
- 3- Valvola di sicurezza (C).
- 4- Regolatori di flusso (D).

**Sensori**

Il rilevamento della posizione di lavoro è affidato a uno o più sensori magnetici di prossimità (optional), che rilevano la posizione dei magneti inseriti nei pistoni.

Quindi, per un corretto funzionamento, è da evitare la vicinanza di forti campi magnetici o di grosse masse di materiale ferromagnetico.

The use of magnetic proximity sensors is therefore to be avoided in the vicinity of large masses of ferromagnetic material or intense magnetic fields as this may cause detection problems.

I sensori utilizzabili sono:

The sensors that can be used are:

CB...

SS...

SS.007.000

PNP

OUT

Magneto-resistive

NPN

OUT

**Sensors**

The operating position is detected by magnetic proximity sensors (optional) through magnets placed on the pistons.

Therefore, to ensure correct functioning, it is recommended to avoid the presence of strong magnetic fields or large ferromagnetic masses near the sensor.

The use of magnetic proximity sensors is therefore to be avoided in the vicinity of large masses of ferromagnetic material or intense magnetic fields as this may cause detection problems.

The sensors that can be used are:

CB...

SS...

SS.007.000

PNP

OUT

Magneto-resistive

NPN

OUT

Einsetzbare Sensoren:

Les capteurs utilisés:

CB...

SS...

SS.007.000

PNP

OUT

Magneto-resistive

NPN

OUT

**Regolazione della corsa**

• A- Regolazione della corsa di chiusura della slitta.  
• B- Regolazione della corsa di apertura della slitta.

Air comprimé in S: apertura della pinza.  
Air comprimé in P: chiusura della pinza.  
Air comprimé in Q: estensione della slitta.  
Air comprimé in R: ritrazione della slitta.

The compressed air must be filtered from 5 to 40 µm.

Maintain the medium selected at the start, lubricated or not, for the complete service life of the unit.

The compressed air must be filtered from 5 to 40 µm.

The compressed air must be filtered from 5 to 40 µm.


The compressed air must be filtered from 5 to 40 µm.

The compressed air must be filtered from 5 to 40 µm.

Never let the unit come into contact with corrosive substances, soldering splashes or abrasive powders as they may damage the unit.

Never let non-authorized persons or objects stand within the operating range of the unit.

Never operate the unit if the machine on which it is fitted does not comply with safety laws and standards of your country.

**Stroke adjustment**

- A - Slide retraction stroke adjustment.
- B - Slide extension stroke adjustment.

Air comprimé in S: apertura della pinza.

Air comprimé in P: chiusura della pinza.

Air comprimé in Q: estensione della slitta.

Air comprimé in R: ritrazione della slitta.

The compressed air must be filtered from 5 to 40 µm.

Maintain the medium selected at the start, lubricated or not, for the complete service life of the unit.

The compressed air must be filtered from 5 to 40 µm.

The compressed air must be filtered from 5 to 40 µm.

The compressed air must be filtered from 5 to 40 µm.

The compressed air must be filtered from 5 to 40 µm.

Never let the unit come into contact with corrosive substances, soldering splashes or abrasive powders as they may damage the unit.

Never let non-authorized persons or objects stand within the operating range of the unit.

Never operate the unit if the machine on which it is fitted does not comply with safety laws and standards of your country.

**GIMATIC**

La pinza e la guida sono alimentate da aria compressa attraverso le aperture laterali e i raccordi dell'aria M3 ed i relativi tubi (non forniti).

Aria compressa in S: apertura della pinza.  
Aria compressa in P: chiusura della pinza.  
Aria compressa in Q: estensione della guida.  
Aria compressa in R: ritrazione della guida.

Il rilevamento della posizione di lavoro è affidato a uno o più sensori magnetici di prossimità (optional), che rilevano la posizione dei magneti inseriti nei pistoni.

Quindi, per un corretto funzionamento, è da evitare la vicinanza di forti campi magnetici o di grosse masse di materiale ferromagnetico.

The use of magnetic proximity sensors is therefore to be avoided in the vicinity of large masses of ferromagnetic material or intense magnetic fields as this may cause detection problems.

I sensori utilizzabili sono:

The sensors that can be used are:

CB...

SS...

SS.007.000

PNP

OUT

Magneto-resistive

NPN

OUT

Einsetzbare Sensoren:

Les capteurs utilisés:

CB...

SS...

SS.007.000

PNP

OUT

Magneto-resistive

NPN

OUT

**Alimentation en air comprimé**

